



Partial elevation detail "B" showing check and removable portion of guide channel being removed from header while door is in hold-open position

